

Revised



Page 1 of 1
Date Sep. 29, 2020
Our ref. FF-200925-R1

SUZUKI MOTOR CORPORATION

Motorcycle Service Group
Overseas Service Department
8686, Miyakoda, Kita, Hamamatsu, Shizuoka, Japan Zip 431-2102
Tel: 81-53-528-8118, Fax: 81-53-528-8141

To : SUZUKI MOTOR OF AMERICA, INC.
Attn. : Managing Director
Service Director or Manager

SUBJECT: GSX250R [L8L7] Headlamp Bulb Market Action

Revised

Dear Sirs and Madams,

We regret to inform you that the headlamp bulb on certain GSX250R [L8L7] may be broken. We would like to request you to take the following actions.

1. Condition

The filament of the headlamp bulb may be broken in a short time and headlamp may go off during driving.

2. Affected Vehicles Information

- (1) Model :GSX250R [L8L7] produced at CHANG ZHOU HAOJUE SUZUKI MOTORCYCLE CO.,LTD.
- (2) Production Period :From Mar. 25 2017 to May. 25 2017
- (3) Vehicles :2,040 units (please find ANNEX1)

3. Action

Please notify this information to your authority as needed. We will announce further information upon determination of its root cause and corrective action. Please procure customer information in advance for getting ready to send a notification, however, continue to hold sending until next decision is made.

We are very sorry for causing inconvenience to you. Your cooperation and assistance will be highly appreciated. If you have any question, please don't hesitate to contact us anytime.

Very truly yours,

Shinji Ishikawa
Department General Manager
Overseas Service Department
SUZUKI MOTOR CORPORATION

Attachment: ANNEX1_America_VIN_List